



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 07/08/2025	LOCALITA' TRISCAR SRL , Via Molino Roero 3, 12100, CUNEO (CN)											
VEICOLO (MARCA - MODELLO - VERSIONE) DUCATO (PC) 35 Mh2 2.3 Multijet 16v 130cv 6m FP						TARGA FV582SP		TELAIO ZFA25000002K43722		1° IMMATRICOLAZ. 04/02/2019		
KM. 13146	COLORE. Bianco Gelato				TIPO SMALTO METALL/DOPPIO							
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO			
5013	Coppa ruota post. 15" DX	S		S		S				59,02	S17	48,99
1030	Fodera cuscino sedile ant. P/sedile ant rotante ne SX	S		S		S				271,33	S17	225,20
0376	Paraurti ant. lat. DX	S	1,40	S		S				245,86	S17	204,06
2000	Paraurti post. lat. P/apert.porta post.extra serie SX	S	0,50	S		S				190,00	S17	157,70
4756	Pannello int. porta post. SX	S		S		S				140,14	S17	116,32
0174	Pannello int. inf. porta post. a battente C/porta DX	S		S		S				141,17	S17	117,17
0174	Pannello int. inf. porta post. a battente SX	S		S		S				137,90	S17	114,46
2187	Porta post. DX	M	0,95	M	2,45	M	4,50					
1935	Parafango ant. DX	M	0,70	M	1,50	M	1,70					
1692	Montante centr. DX	M	0,90	M	2,00	M	2,60					
2012	Parete lat. post. DX	L	0,90	L	0,50	L	2,30					
	sottoporta		1,00		2,50		3,20					
	presa in carico									0,01		0,01
0376	Scomposizione paraurti DX											
2000	Scomposizione paraurti SX											
TOTALE TEMPI		SR 6,35		LA 8,95		VE 14,30		ME 0,00		TOTALE RICAMBI 983,91		
ORE SUPPLEMENTO DOPPIO STRATO 15 % 2,15		ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE 1,65		ORE AGGIUNTIVE PER VERNICIATURA 1,60		TOTALE ORE SUPPLEMENTARI 5,40		TOTALE ORE VERNICIATURA 19,70				
NOTE Pneumatico ant dx - Pirelli - 215/70/15 - estivo - 9 mm Pneumatico ant sx - Pirelli - 215/70/15 - estivo - 9 mm Pneumatico post dx - Pirelli - 215/70/15 - estivo - 9 mm Pneumatico post sx - Pirelli - 215/70/15 - estivo - 9 mm Periziato con tempo sereno						RICAMBI		983,91				
						MATER. DI CONSUMO ORE 19,70 €/ORA 12,00		236,40				
						USO DIME		0,00				
						SMALTIMENTO RIFIUTI		25,00				
						MANODOPERA CARR. ORE 35,00 €/ORA 45,00		1575,00				
						MANODOPERA MECC. ORE 0,00 €/ORA 45,00		0,00				
						IMPONIBILE		2820,31				
						IVA		620,47				
						TOTALE COMPLESSIVO		3440,78				
CODICE PERITO 351	FIRMA			RUOLO N. 0000		FERMO TECNICO GIORNI 5			FOGLIO 1			

Legenda

FF:Forfait

PRM:Promemoria

DE:Difetto esecuzione

GR:Grandine

MAC:Macchiato

NU:Normale usura

SRG:Adesivi



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 07/08/2025	LOCATION TRISCAR SRL , Via Molino Roero 3, 12100, CUNEO (CN)												
VEHICLE (BRAND - MODEL - VERSION) DUCATO (PC) 35 Mh2 2.3 Multijet 16v 130cv 6m FP					PLATE FV582SP		CHASSIS ZFA25000002K43722		1st REGISTRATION. 04/02/2019				
KM. 13146	COLOR. Bianco gelato			ENAMEL TYPE Metall/doppio									
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded		
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME				
5013	Coppa wheel rear 15" Dx	S		S		S				59,02	S17	48,99	
1030	Lining cushion seat front p/sedile front rotating Sx	S		S		S				271,33	S17	225,20	
0376	Lateral front bumper Dx	S	1,40	S		S				245,86	S17	204,06	
2000	Paraurti rear lat. p/apert.porta post.extra serie Sx	S	0,50	S		S				190,00	S17	157,70	
4756	Internal panel of rear door Sx	S		S		S				140,14	S17	116,32	
0174	Pannello int. lower brings rear a swing c/porta sw Dx	S		S		S				141,17	S17	117,17	
0174	Lower interior panel of side-hinged tailgate Sx	S		S		S				137,90	S17	114,46	
2187	Rear door Dx	M	0,95	M	2,45	M	4,50						
1935	Front fender Dx	M	0,70	M	1,50	M	1,70						
1692	Centre pillar Dx	M	0,90	M	2,00	M	2,60						
2012	Rear lateral wall Dx	L	0,90	L	0,50	L	2,30						
	Sills		1,00		2,50		3,20						
	Taking charge									0,01		0,01	
0376	Bumper dismantling Dx												
2000	Bumper dismantling Sx												
TOTAL TIMES				SR 6,35		LA 8,95		VE 14,30		ME 0,00		TOTAL SPARE PARTS 983,91	
DOUBLE LAYER SUPPLEMENT HOURS 15 % 2,15		FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS 1,65		ADDITIONAL HOURS FOR PAINTING 1,60		TOTAL ADDITIONAL HOURS 5,40		TOTAL PAINTING HOURS 19,70					
NOTE Right front tire - Pirelli - 215/70/15 - Summer - 9 mm Left front tire - Pirelli - 215/70/15 - Summer - 9 mm Right rear tire - Pirelli - 215/70/15 - Summer - 9 mm Left rear tire - Pirelli - 215/70/15 - Summer - 9 mm Appraised in clear weather								SPARE PARTS		983,91			
								MATER. CONSUMPTION HOURS 19,70€/HOUR 12,00		236,40			
								USE TEMPLATES		0,00			
								WASTING DISPOSAL		25,00			
								LABOR CARR. HOURS 35,00€/HOUR 45,00		1575,00			
								LABOR MECH. HOURS 0,00 €/HOUR 45,00		0,00			
								TAXABLE		2820,31			
								VAT		620,47			
								TOTAL		3440,78			
EXPERT CODE 351	SIGNATURE			ROLE NUMBER 0000			STOP TECHNICIAN DAYS 5			SHEET 1			

Legend

Ff: forfait

Prm: reminder

De: lack of execution

Gr: hail

Mac: stained

Nu: normal wear

Srg: stickers