



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 18/08/2025		LOCALITA' BRASIELLO CARSERVICE SRL - STOCK ROOM, Via Oreste Salomone, 72, 20138, Milano (MI)										
VEICOLO (MARCA - MODELLO - VERSIONE) FORD TRANSIT CUSTOM 280 L1H1 TREND 2.0 ECOBLUE MHEV 130 CV FP						TARGA GK528ZL		TELAIO WF0YXXTTGYNU33379		1° IMMATRICOLAZ. 18/07/2022		
KM. 48402		COLORE. Frozen White			TIPO SMALTO METALL/DOPPIO							
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO			
	Pannelli interni legno sx e dx	S		S		S				180,00	S17	149,40
	Pneum. post sx Non conforme al Cds											
	Pneum. post dx Non conforme al Cds											
	Pneum. ant dx Danneggiato											
	Kit gonfiaggio									100,00		100,00
	Seconda chiave mancante											
2168	Porta ant. SX	L	1,20	L	1,20	L	1,90					
2004	Parete lat. SX	L	1,40	L	1,20	L	6,10					
0174	Pannello int. inf. porta post. a battente SX	S		S		S				46,66	S17	38,73
2035	Passaruota post. est. SX	L	1,00	L	1,00	L	1,00					
2624	Pannello int. porta carico lat. scorrevole Inf./li SX	S		S		S				62,22	S17	51,64
2035	Passaruota post. est. DX	L	1,00	L	1,00	L	1,00					
0174	Pannello int. inf. porta post. a battente DX	S		S		S				38,08	S17	31,61
2177	Porta carico post. a battente Lamierata p/tetto al SX	L	0,45	L	0,85	L	1,60					
2177	Porta carico post. a battente Lamierata DX	L	0,35	L	0,85	L	1,60					
2012	Parete lat. post. P/porta lat. scorr. DX	L	1,00	L	2,00	L	3,00					
2175	Porta carico lat. scorrevole 05/19< DX	L	0,70	L	1,20	L	2,10					
2168	Porta ant. DX	L	0,60	L	0,85	L	1,45					
5003	Paraurti ant. parte sup. P/disco ruota 15/16/18" p	L	1,00	L		L	2,00					
5003	Scomposizione paraurti		1,00									
TOTALE TEMPI		SR 9,70		LA 10,15		VE 21,75		ME 0,00		TOTALE RICAMBI 371,38		
ORE SUPPLEMENTO DOPPIO STRATO 15 % 3,26		ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE 2,50			ORE AGGIUNTIVE PER VERNICIATURA 1,60			TOTALE ORE SUPPLEMENTARI 7,36		TOTALE ORE VERNICIATURA 29,11		
NOTE Pneumatico ant dx - Goodyear - 215/65/15 - estivo - 2.8 mm Pneumatico ant sx - Goodyear - 215/65/15 - estivo - 4.9 mm Pneumatico post dx - Goodyear - 215/65/15 - estivo - 1.3 mm Pneumatico post sx - Goodyear - 215/65/15 - estivo - 1.2 mm Periziato con tempo sereno								RICAMBI		371,38		
								MATER. DI CONSUMO ORE 29,11 €/ORA 12,00		349,32		
								USO DIME		0,00		
								SMALTIMENTO RIFIUTI		25,00		
								MANODOPERA CARR. ORE 48,96 €/ORA 45,00		2203,20		
								MANODOPERA MECC. ORE 0,00 €/ORA 45,00		0,00		
								IMPONIBILE		2948,90		
								IVA		648,76		
								TOTALE COMPLESSIVO		3597,66		
CODICE PERITO 302		FIRMA			RUOLO N. 0000		FERMO TECNICO GIORNI			7		FOGLIO 1

Legenda

FF:Forfait

PRM:Promemoria

DE:Difetto esecuzione

GR:Grandine

MAC:Macchiato

NU:Normale usura

SRG:Adesivi



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 18/08/2025	LOCATION BRASIELLO CARSERVICE SRL - STOCK ROOM, Via Oreste Salomone, 72, 20138, Milano (MI)											
VEHICLE (BRAND - MODEL - VERSION) FORD TRANSIT CUSTOM 280 L1H1 TREND 2.0 ECOBLUE MHEV 130 CV FP					PLATE GK528ZL		CHASSIS WF0YXXTTGYNU33379		1st REGISTRATION. 18/07/2022			
KM. 48402	COLOR. Frozen white			ENAMEL TYPE Metall/doppio								
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded	
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME			
	Pannelli interior legno left e right	S		S		S				180,00	S17	149,40
	Tire rear left non compliant to the cds											
	Tire rear right non compliant to the cds											
	Tire front right danneggiato											
	Tire inflation kit									100,00		100,00
	Second key missing											
2168	Front door Sx	L	1,20	L	1,20	L	1,90					
2004	Lateral wall Sx	L	1,40	L	1,20	L	6,10					
0174	Lower interior panel of side-hinged tailgate Sx	S		S		S				46,66	S17	38,73
2035	Outer rear wheelhouse Sx	L	1,00	L	1,00	L	1,00					
2624	Pannello int. brings load lat. sliding inf./liv.ma Sx	S		S		S				62,22	S17	51,64
2035	Outer rear wheelhouse Dx	L	1,00	L	1,00	L	1,00					
0174	Lower interior panel of side-hinged tailgate Dx	S		S		S				38,08	S17	31,61
2177	Porta load rear a swing lamierata p/tetto high Sx	L	0,45	L	0,85	L	1,60					
2177	Porta load rear a swing lamierata Dx	L	0,35	L	0,85	L	1,60					
2012	Parete lat. rear p/porta lat. sliding Dx	L	1,00	L	2,00	L	3,00					
2175	Porta load lat. sliding 05/19< Dx	L	0,70	L	1,20	L	2,10					
2168	Front door Dx	L	0,60	L	0,85	L	1,45					
5003	Paraurti front part sup. p/disco wheel 15/16/18" p	L	1,00	L		L	2,00					
5003	Bumper dismantling		1,00									
TOTAL TIMES		SR	LA		VE		ME		TOTAL SPARE PARTS			
			9,70		10,15		21,75		0,00		371,38	
DOUBLE LAYER SUPPLEMENT HOURS 15 % 3,26		FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS 2,50		ADDITIONAL HOURS FOR PAINTING 1,60		TOTAL ADDITIONAL HOURS 7,36		TOTAL PAINTING HOURS 29,11				
NOTE Right front tire - Goodyear - 215/65/15 - Summer - 2.8 mm Left front tire - Goodyear - 215/65/15 - Summer - 4.9 mm Right rear tire - Goodyear - 215/65/15 - Summer - 1.3 mm Left rear tire - Goodyear - 215/65/15 - Summer - 1.2 mm Appraised in clear weather								SPARE PARTS		371,38		
								MATER. CONSUMPTION HOURS 29,11€/HOUR 12,00		349,32		
								USE TEMPLATES		0,00		
								WASTING DISPOSAL		25,00		
								LABOR CARR. HOURS 48,96€/HOUR 45,00		2203,20		
								LABOR MECH. HOURS 0,00 €/HOUR 45,00		0,00		
								TAXABLE		2948,90		
								VAT		648,76		
								TOTAL		3597,66		
EXPERT CODE 302	SIGNATURE			ROLE NUMBER 0000			STOP TECHNICIAN DAYS 7			SHEET 1		

Legend

Ff: forfait

Prm: reminder

De: lack of execution

Gr: hail

Mac: stained

Nu: normal wear

Srg: stickers